

10/13/95 A.2



INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT
100 NORTH SENATE AVENUE
P. O. BOX 6015
INDIANAPOLIS, INDIANA 46206-6015

DATE: 10-13-95

TO: Sheri Bianchin	TELEFAX # 312-886-4071
COMPANY/DIVISION: EPA-Superfund	TELEPHONE # 312-886-4745

FROM: K. Grindstaff	TELEPHONE # 317-233-0575
COMMISSION & SECTION: OER/TSB-Geology	NUMBER OF PAGES: 2

COMMENTS: Sheri-These are my comments. They are the same as what I sent via e-mail to Steve yesterday.
--

IDEM LOCATION		FAX NUMBER	CONFIRM NUMBER
INDIANA GOVERNMENT CENTER-NORTH		(AREA CODE 317)	
OMBA	13TH FLOOR	232-5539	232-8180
OSHWB FILE ROOM	11TH FLOOR	232-3403	232-3399
ENFORCEMENT	13TH FLOOR	232-5968	233-5529
IDEM COMMISSIONER	13TH FLOOR	232-8564	233-8162
WATER MANAGEMENT	12TH FLOOR	232-8637	232-8670
WATER MANAGEMENT	11TH FLOOR	232-8406	232-8476
DRINKING WATER	11TH FLOOR	233-4165	233-4222
AIR MGMT.-ASBESTOS	10TH FLOOR	233-3257	233-3861
AIR MANAGEMENT	10TH FLOOR	233-5967	232-5586
LEGAL COUNSEL	13TH FLOOR	233-5517	232-8753
EXTERNAL AFFAIRS	13TH FLOOR	232-8564	232-8560
ENVIRON. RESP. & MIS	12TH FLOOR	233-6358	233-6352
WATER MANAGEMENT	BRADBURY	243-5092	243-5036
NORTHWEST OFFICE	GARY, IN	(219) 881-6745	(219) 881-6712

US EPA RECORDS CENTER REGION 5



464696

Date: Oct 12 1995

To: steve mangion (SMTP), H. Grejda (HGREJ)

From: K. Grindstaff (KHEWI)

Indiana Dept. Env. Mgmt PO Box 6015 Indy 46206-6015 Ge-
ologist

(317)233-0575, Kathleen Grindstaff

Hi Steve - I decided this would be the best way for us to communicate, since you're having the conference call day from hell. Rob and I just spoke, and the following comments are the result of our discussion: 1) Comment 2 of Sheri's letter should also include P-38 for repair. 2) Comment 6 was unclear to me. I think perhaps what you're referring to is that Figure 2 of their memo did not include the elevations with the contours. It would be helpful to spell out what was incorrect, so they fix it next time. 3) Comment 7 was confusing to me. I think the intention is that their additional proposed piezometer locations should be replaced with the figure attached to her draft letter (showing Rob's locations), along with the locations in Comments 2 and 4, and the existing network. It might just be me, since it's been a long day. If you feel it is pretty clear, leave it.

Additional things that I noticed from my review were that MW-19 was not included on Figure 1. It should be included in the future, or rationale provided for its omission. In addition, a location indicated as SG-11 is provided in the RI (figure 4-1) and Figure 4-1 of the Predesign report. This should be included in the network as well (note that Rob's additional staff gauges would then be SG-12 and 13). Let me know if you have any questions. Thanks for the opportunity to comment. Talk to you soon, Kathy